

Technical Support: Complaint – Taycan Alarm Triggering

Posted by Alexander Matheis Nov 16, 2021

Model affected Model Year

Taycan/Taycan Cross Turismo (Y1A/Y1B) 2020 and newer

Complaint

Customers complain about the alarm triggering or going off at random. Technicians may find fault codes indicating the interior monitoring sensor as cause for the alarm trigger.

If the complaint occurs repeatedly, the customer has the option of deactivating the interior monitoring by pressing the vehicle lock button on the key twice.

Cause

This topic is currently being analyzed.

Correction

No solution is currently available. Do not exchange the roof console with interior monitoring sensor at this point in time.

A technical solution will be communicated as soon as it is available.

790 Views Tags: complaint, alarm, taycan, y1a, y1b