

# 2020 Porsche Taycan

## Weak Key Fob – Failure to Recognize



When the Porsche Taycan proximity key fob batteries become weak the vehicle may have difficulty acknowledging its presence and fail to turn on or start.

Placing the fob near the designated area will aid in starting the vehicle.

**The designated area in this model is in the rear cup holder.**



**Immediately replace the weak key fob battery.**