

LINE	OPCODE	TECH	TYPE	HOURS	LIST	NET	TOTAL
A	ASA2	Occupant classification may turn off air bag					
	99BMZ	ASA2 Occupant classification may turn off air bag					
	6988	ISP					(N/C)
PARTS:	0.00	LABOR:	0.00	OTHER:	0.00	TOTAL LINE A:	0.00
20199							

B	PERFORM A COMPLIMENTARY MULTI POINT INSPECTION						
	MP	PERFORM A COMPLIMENTARY MULTI POINT INSPECTION					
	6988	ISP					(N/C)
PARTS:	0.00	LABOR:	0.00	OTHER:	0.00	TOTAL LINE B:	0.00
20199	PERFORMED MULTI-POINT INSPECTION						

C	20,000 MILE MAINTENANCE SERVICE QUOTED CUSTOMER \$2,325.41						
	CAUSE: 2 YEAR/20K SERVICE						
	B008A020000	20,000 MILE MAINTENANCE SERVICE					
		QUOTED CUSTOMER \$2,325.41					
	6988	CPM				1249.75	1249.75
	1	976-819-429 DUST AND POLLEN FILTER					142.72
	2	000-043-210-82 BRAKE FLUID					120.12
	1	958-012-619-A TYRE SEALANT					247.08
	1	088 MULTI-PURPOSE CLEANER					13.44
	1	7083 FRIGI-FRESH 1OZ					10.50
	1	D-007-000-A2 SILICON LUBRICANT SPRAY					67.52
	1	9J1-955-425-DY 1 SET: WIPER BLADES					97.80
	1	999-611-108-00 BATTERY					22.17
PARTS:	721.35	LABOR:	1249.75	OTHER:	0.00	TOTAL LINE C:	1971.10
20199	2 YEAR/20K SERVICE PERFORMED	20K SERVICE					

D	PERFORM OPEN CAMPAIGN/RECALLASA2						
	CAUSE: Replace front seat cushion						
	RECALL	PERFORM OPEN CAMPAIGN/RECALLASA2					
	6988	W					(N/C)
	1	V04-015-800-DK REPAIR SET FOR SEAT OCCUPIED					

WARRANTY DISCLAIMER: ALL PARTS AND ACCESSORIES ARE SOLD AND ALL REPAIRS ARE PROVIDED BY THE DEALERSHIP AS-IS. THE DEALERSHIP HEREBY EXPRESSLY DISCLAIMS ALL WARRANTIES, EXPRESS AND IMPLIED, INCLUDING ANY IMPLIED WARRANTIES OF MERCHANTABILITY AND FITNESS FOR A PARTICULAR PURPOSE, AND NEITHER ASSUMES NOR AUTHORIZES ANY OTHER PERSON TO ASSUME FOR IT ANY LIABILITY IN CONNECTION WITH THE SALE OF PARTS OR PRODUCTS OR THE REPAIR. THE ONLY WARRANTIES ON PARTS AND ACCESSORIES OR REPAIRS ARE THOSE WHICH MAY BE OFFERED BY THE VEHICLE MANUFACTURER OR THE PARTS MANUFACTURER OR DISTRIBUTOR AND ONLY SUCH MANUFACTURER OR DISTRIBUTOR SHALL BE LIABLE FOR PERFORMANCE UNDER SUCH WARRANTIES. CUSTOMER SHALL NOT BE ENTITLED TO RECOVER FROM THE DEALERSHIP ANY CONSEQUENTIAL DAMAGES, DAMAGES TO PROPERTY, DAMAGES FOR LOSS OF USE, LOSS OF TIME, LOSS OF PROFIT OR INCOME, OR ANY OTHER INCIDENTAL DAMAGES.

By signing below, you acknowledge that you were notified of and authorized the Dealership to perform the services/repairs itemized in this Invoice and that you received (or had the opportunity to inspect) any replaced parts as requested by you. The vehicle is being returned to you in exchange for your payment of the Amount Due.

*SHOP SUPPLY COSTS:	DESCRIPTION	TOTALS
We have added a charge equal to 13.5% of the total cost of labor and parts, not to exceed \$83.87, to the Repair Order for shop supplies used in connection with this repair.	LABOR AMOUNT	
	PARTS AMOUNT	
	GAS, OIL, LUBE	
	SUBLET AMOUNT	
	MISC. CHARGES *	
	TOTAL CHARGES	
ALL PARTS ARE NEW UNLESS OTHERWISE INDICATED.	LESS INSURANCE	
	SALES TAX	
	PLEASE PAY THIS AMOUNT	

DATE _____ CUSTOMER SIGNATURE _____ AUTHORIZED DEALERSHIP REPRESENTATIVE SIGNATURE _____

LINE	OPCODE	TECH	TYPE	HOURS	LIST	NET	TOTAL
							(N/C)
							(N/C)
							(N/C)
							0.00
PARTS: 0.00 LABOR: 0.00 OTHER: 0.00 TOTAL LINE D:							0.00

20199 Replace front seat cushion
 Scope 6:
 Replace front seat cushion (passenger side)
 - only relevant for vehicles with the following equipment
 combination: ?Comfort seats front (14-way, electric) with memory
 package? (M-no. Q2J) and ?Front seat ventilation? (M-no. 4D3) or ?Front
 massage function incl. front seat ventilation? (M-no. 4D5)
 Labor time:
 Replace front seat cushion (passenger side) ; Labor time 151 TU
 Includes Install and remove front seat
 Remove and install control panel trim
 Remove and install front seat trim panel
 Replace front seat cushion
 Connect and disconnect Porsche Tester
 Re-calibrate occupant detection control unit
 Carry out standardisation of the seat motors
 Required parts:
 V04015800DK Repair kit for seat occupancy detection 1 piece
 9A700748300 External hexalobular screw 4 pieces
 ?Damage number ASA2 099 000 2

 E** PERFORM TAYCAN FOUR WHEEL ALIGNMENT FRONT TIRES HAVE ALIGNMENT WEAR
 CAUSE: ALIGNMENT
 4WATAYCAN PERFORM TAYCAN FOUR WHEEL ALIGNMENT
 FRONT TIRES HAVE ALIGNMENT WEAR
 6988 CTI 750.00 750.00
 PARTS: 0.00 LABOR: 750.00 OTHER: 0.00 TOTAL LINE E: 750.00
 20199 ALIGNMENT PERFORMED FOUR WHEEL ALIGNMENT, ADJUST CASTER,
 CAMBER AND TOE AS NEEDED

WARRANTY DISCLAIMER: ALL PARTS AND ACCESSORIES ARE SOLD AND ALL REPAIRS ARE PROVIDED BY THE DEALERSHIP AS-IS. THE DEALERSHIP HEREBY EXPRESSLY DISCLAIMS ALL WARRANTIES, EXPRESS AND IMPLIED, INCLUDING ANY IMPLIED WARRANTIES OF MERCHANTABILITY AND FITNESS FOR A PARTICULAR PURPOSE, AND NEITHER ASSUMES NOR AUTHORIZES ANY OTHER PERSON TO ASSUME FOR IT ANY LIABILITY IN CONNECTION WITH THE SALE OF PARTS OR PRODUCTS OR THE REPAIR. THE ONLY WARRANTIES ON PARTS AND ACCESSORIES OR REPAIRS ARE THOSE WHICH MAY BE OFFERED BY THE VEHICLE MANUFACTURER OR THE PARTS MANUFACTURER OR DISTRIBUTOR AND ONLY SUCH MANUFACTURER OR DISTRIBUTOR SHALL BE LIABLE FOR PERFORMANCE UNDER SUCH WARRANTIES. CUSTOMER SHALL NOT BE ENTITLED TO RECOVER FROM THE DEALERSHIP ANY CONSEQUENTIAL DAMAGES, DAMAGES TO PROPERTY, DAMAGES FOR LOSS OF USE, LOSS OF TIME, LOSS OF PROFIT OR INCOME, OR ANY OTHER INCIDENTAL DAMAGES.		*SHOP SUPPLY COSTS:	DESCRIPTION	TOTALS
By signing below, you acknowledge that you were notified of and authorized the Dealership to perform the services/repairs itemized in this invoice and that you received (or had the opportunity to inspect) any replaced parts as requested by you. The vehicle is being returned to you in exchange for your payment of the Amount Due.		We have added a charge equal to 13.5% of the total cost of labor and parts, not to exceed \$83.87, to the Repair Order for shop supplies used in connection with this repair.	LABOR AMOUNT	
			PARTS AMOUNT	
			GAS, OIL, LUBE	
			SUBLET AMOUNT	
			MISC. CHARGES *	
			TOTAL CHARGES	
			LESS INSURANCE	
SALES TAX				
DATE	CUSTOMER SIGNATURE	AUTHORIZED DEALERSHIP REPRESENTATIVE SIGNATURE	PLEASE PAY THIS AMOUNT	

LINE OPCODE TECH TYPE HOURS LIST NET TOTAL

ESTIMATE: 750.00 30DEC25 14:48 SA: 8405

CONTACT:

ESTIMATE: 0.00 30DEC25 08:54 SA: 8405

CONTACT:

YOUR COMPLETE SATISFACTION IS OUR
 NUMBER 1 PRIORITY. PLEASE CONTACT OUR SERVICE
 DEPARTMENT IF YOU HAVE ANY CONCERNS, QUESTIONS
 OR COMMENTS REGARDING YOUR SERVICE. THANK YOU
 FOR YOUR BUSINESS AND WE LOOK FORWARD TO
 SEEING YOU AGAIN. (703)684-6660

48.31

WARRANTY DISCLAIMER: ALL PARTS AND ACCESSORIES ARE SOLD AND ALL REPAIRS ARE PROVIDED BY THE DEALERSHIP AS-IS. THE DEALERSHIP HEREBY EXPRESSLY DISCLAIMS ALL WARRANTIES, EXPRESS AND IMPLIED, INCLUDING ANY IMPLIED WARRANTIES OF MERCHANTABILITY AND FITNESS FOR A PARTICULAR PURPOSE, AND NEITHER ASSUMES NOR AUTHORIZES ANY OTHER PERSON TO ASSUME FOR IT ANY LIABILITY IN CONNECTION WITH THE SALE OF PARTS OR PRODUCTS OR THE REPAIR. THE ONLY WARRANTIES ON PARTS AND ACCESSORIES OR REPAIRS ARE THOSE WHICH MAY BE OFFERED BY THE VEHICLE MANUFACTURER OR THE PARTS MANUFACTURER OR DISTRIBUTOR AND ONLY SUCH MANUFACTURER OR DISTRIBUTOR SHALL BE LIABLE FOR PERFORMANCE UNDER SUCH WARRANTIES. CUSTOMER SHALL NOT BE ENTITLED TO RECOVER FROM THE DEALERSHIP ANY CONSEQUENTIAL DAMAGES, DAMAGES TO PROPERTY, DAMAGES FOR LOSS OF USE, LOSS OF TIME, LOSS OF PROFIT OR INCOME, OR ANY OTHER INCIDENTAL DAMAGES.
 By signing below, you acknowledge that you were notified of and authorized the Dealership to perform the services/repairs itemized in this Invoice and that you received (or had the opportunity to inspect) any replaced parts as requested by you. The vehicle is being returned to you in exchange for your payment of the Amount Due.

***SHOP SUPPLY COSTS:**
 We have added a charge equal to 13.5% of the total cost of labor and parts, not to exceed \$83.87, to the Repair Order for shop supplies used in connection with this repair.

ALL PARTS ARE NEW UNLESS OTHERWISE INDICATED.

DESCRIPTION	TOTALS
LABOR AMOUNT	1999.75
PARTS AMOUNT	721.35
GAS, OIL, LUBE	0.00
SUBLET AMOUNT	0.00
MISC. CHARGES *	83.87
TOTAL CHARGES	2804.97
LESS INSURANCE	0.00
SALES TAX	48.31

DATE CUSTOMER SIGNATURE AUTHORIZED DEALERSHIP REPRESENTATIVE SIGNATURE

PLEASE PAY THIS AMOUNT 2853.28